

Tree	No	Species	BS Category	Recommendations
T	1	Pear	B	Crown lift to 3m above ground level, remove deadwood
T	2	Sycamore	B	Fell to ground level to facilitate development
T	3	Cypress	C	Fell to ground level to facilitate development
T	4	Ash	C	Fell to ground level to facilitate development
T	5	Ash	C	Fell to ground level to facilitate development
T	6	Ash	C	Fell to ground level to facilitate development
T	7	Ash	C	Fell to ground level to facilitate development
T	8	Hawthorn	C	Fell to ground level to facilitate development
T	11	Ash	U	Fell to ground level for arboricultural reasons
T	12	Ash	B	Fell to ground level to facilitate development
T	14	Apple	C	Fell to ground level to facilitate development
G	15	Ash Goat willow	C	Fell to ground level to facilitate development
T	17	Ash	C	Fell to ground level to facilitate development
T	18	Oak	C	Fell to ground level to facilitate development
T	19	Ash	C	Fell to ground level to facilitate development
T	20	Oak	C	Fell to ground level to facilitate development
T	21	Ash	C	Fell to ground level to facilitate development
T	24	Cherry	B	Fell to ground level to facilitate development
T	25	Ash	B2	Fell to ground level to facilitate development
T	26	Cherry	U	Fell to ground level to facilitate development
T	27	Oak	B	Fell to ground level to facilitate development
T	28	Oak	C	Fell to ground level to facilitate development
T	30	Cherry	U	Fell to ground level for arboricultural reasons
T	31	Cherry	U	Fell to ground level for arboricultural reasons
T	32	Goat willow	U	Fell to ground level for arboricultural reasons
T	33	Willow	U	Fell to ground level for arboricultural reasons
T	34	Ash	C	Fell to ground level to facilitate development
T	35	Oak	C	Fell to ground level to facilitate development
T	37	Oak	C	Fell to ground level to facilitate development
T	52	Oak	C	Fell to ground level to facilitate development
T	53	Oak	C	Fell to ground level to facilitate development
T	54	Sycamore	U	Fell to ground level for arboricultural reasons
G	56	Blackthorn Ash Goat willow Silver birch Apple sp. Crack willow	C	Prune back to proposed residential fence lines
T	57	Plum	U	Fell to ground level for arboricultural reasons
T	58	Plum	U	Fell to ground level for arboricultural reasons
T	59	Willow	U	Fell to ground level for arboricultural reasons
T	60	Willow	U	Fell to ground level for arboricultural reasons
G	61	Hawthorn Elder Plum	C	Partial fell to ground level to facilitate development
T	64	Oak	B2	Fell to ground level to facilitate development

G	72	Elder Hawthorn Poplar Plum	C	Fell to ground level to facilitate development
T	74	Oak	B	Fell to ground level to facilitate development
T	79	Oak	B2	Fell to ground level to facilitate development
T	80	Oak	B2	Fell to ground level to facilitate development
G	81	Hawthorn Blackthorn Ash Plum	C	Partial fell to ground level to facilitate development
T	83	Ash	C	Fell to ground level to facilitate development
T	84	Plum	C	Fell to ground level to facilitate development
G	85	Hawthorn Apple	C	Fell to ground level to facilitate development
T	86	Ash	C	Fell to ground level to facilitate development
T	87	Ash	C	Fell to ground level to facilitate development
T	88	Goat willow	C	Fell to ground level to facilitate development
G	89	Ash	C	Fell to ground level to facilitate development
G	90	Blackthorn	C	Fell to ground level to facilitate development
G	91	Fir Plum	C	Fell to ground level to facilitate development
G	92	Hawthorn Blackthorn Ash Turkey oak Elder Laurel Buddleja Blackberry	C	Fell to ground level to facilitate development
T	93	Laurel	C	Fell to ground level to facilitate development
T	94	Cypress	C	Fell to ground level to facilitate development
T	95	Cypress	C	Fell to ground level to facilitate development
G	96	Hawthorn Holly Ash Apple Blackberry Elder	C	Partial fell to ground level to facilitate development
T	99	Robinia	C	Fell to ground level to facilitate development
T	100	Yew	C	Fell to ground level to facilitate development
T	101	Lime	B1	Fell to ground level to facilitate development
T	105	Oak	C	Fell to ground level to facilitate development
T	106	Ash	C	Fell to ground level to facilitate development
T	107	Oak	C	Fell to ground level to facilitate development
G	108	Oak	C	Fell to ground level to facilitate development
T	117	Oak	B	Fell to ground level to facilitate development
T	124	Ash	U	Fell to ground level to facilitate development

NOTE:

All tree works should comply with BS 3998 (2010) - Recommendations. If necessary, appropriate checks by a suitably qualified ecologist should be made before tree works are undertaken, and all works should only be carried out once planning permission has been granted and any pre-commencement planning conditions relating to tree work have been discharged